

RELEASE NOTES

for

BRASS-PAD™ Version 3.2

April 2015

General

The BRASS™ incident tracking system can be found at www.wydot-brass.com. Users without an account on the incident tracking system can request an account by clicking on the "Open a Technical Support Account" link/button and e-mailing the address or calling the phone number listed. A username and password will be created and sent to the user. All BRASS™ technical support questions should be logged in this system.

Program Maintenance

The following issues were addressed for this release. The incident number is listed in parentheses after each issue if applicable.

Maintenance

- Verified the program is up-to-date with the AASHTO LRFD *Bridge Design Specifications*, 7th Edition, 2014, with 2015 Interim Revisions. (764)
- Updated the BRASS™ Suite program descriptions in the help system. (778)

Bug Fixes

- Fixed error which made the output file available to open only after running analysis. (760)
- Fixed error in output to show all digits in longitudinal Moment Transferred By The Bearing. (761)
- Updated Example2.pad to result in a successful design. (762)