

RELEASE NOTES

for

BRASS-POLE™ Version 4.6

June 2018

General

The BRASS™ incident tracking system can be found at www.wydot-brass.com. Users without an account for the incident tracking system can request an account by clicking on the "Open a Technical Support Account" link/button and e-mailing the address or calling the phone number listed. A username and password will be created and sent to the user. All BRASS™ technical support questions should be logged in this system.

Program Maintenance

The following issues were addressed for this release. The incident number is listed in parentheses after each issue if applicable.

Maintenance

- Updated the BRASS-POLE engine to Intel Parallel Studio XE 2018. (1331)
- Updated menu items to match with other BRASS programs. (1363)
- Revised location of non-static files used by or generated from BRASS-POLE. (1369)

Bug Fixes

- Fixed error which caused the output to not display properly if the filename extension (.bpl) included capital letters. (1313)
- Fixed error with pole base torsion calculation. (1379)