

2015 OCCUPANTS IN INJURY CRASHES WITH SEAT POSITION / INJURY STATUS

	Incap	Non-Incap	Possible	No Injury	Unknown	Total
Bus Passenger	0	0	1	1	0	2
Driver	300	1045	1187	1742	94	4368
Fourth Row Left	0	0	1	3	0	4
Fourth Row Middle	0	2	1	2	0	5
Fourth Row Right	0	1	1	2	0	4
Front Row Middle	4	15	2	11	0	32
Front Row Right	55	267	287	510	10	1129
Lying Down Front Seat	0	2	0	1	0	3
Lying Down Other Seat	1	0	0	3	0	4
Motorcycle Passenger	3	18	11	9	1	42
Other (explain in narrative)	0	10	1	1	0	12
Other Enclosed Area	0	0	1	2	0	3
Other Row (i.e. Bus, Van)	1	0	2	8	0	11
Passenger Front Row Left (Vehi	0	3	1	6	0	10
Riding on MV Exterior	2	0	0	0	0	2
Second Row Left	6	42	45	189	4	286
Second Row Middle	6	16	13	78	2	115
Second Row Right	8	46	62	225	6	347
Sleeper Section of Cab	2	13	8	21	0	44
Third Row Left	1	3	3	16	0	23
Third Row Middle	0	0	2	7	0	9
Third Row Right	0	5	3	25	0	33
Trailing Unit	1	0	0	0	0	1
Unknown (explain in narrative)	0	6	1	60	1	68
Total	390	1494	1633	2922	118	6557