

2016 OCCUPANTS IN INJURY CRASHES WITH SEAT POSITION / INJURY STATUS

	Incap	Non-Incap	Possible	No Injury	Unknown	Total
Bus Passenger	0	0	2	0	0	2
Driver	231	968	966	1477	71	3713
Fourth Row Left	0	1	0	0	0	1
Fourth Row Middle	0	0	0	1	0	1
Fourth Row Right	0	1	0	2	0	3
Front Row Middle	1	8	4	5	0	18
Front Row Right	54	224	271	467	12	1028
Lying Down Other Seat	2	2	4	1	0	9
Motorcycle Passenger	4	14	6	0	0	24
Other (explain in narrative)	0	4	6	12	0	22
Other Enclosed Area	0	2	0	5	0	7
Passenger Front Row Left (Vehi	0	2	0	2	0	4
Riding on MV Exterior	1	2	0	1	0	4
Second Row Left	6	39	44	169	3	261
Second Row Middle	3	14	12	64	0	93
Second Row Right	6	43	47	173	6	275
Sleeper Section of Cab	2	10	13	16	0	41
Third Row Left	0	2	3	11	1	17
Third Row Middle	0	1	2	9	0	12
Third Row Right	0	1	2	19	1	23
Unenclosed Cargo Area	0	2	2	0	0	4
Unknown (explain in narrative)	3	4	8	62	4	81
Total	313	1344	1392	2496	98	5643