

**2017 OCCUPANTS IN INJURY CRASHES
WITH SEAT POSITION / INJURY STATUS**

	Suspected Serious	Suspected Minor	Possible	No Injury	Unknown	Total
Bus Passenger	0	0	3	0	0	3
Driver	262	972	1040	1510	72	3856
Fourth Row Left	0	0	0	1	0	1
Fourth Row Middle	0	0	0	1	0	1
Fourth Row Right	0	0	0	1	0	1
Front Row Middle	0	9	2	10	1	22
Front Row Right	34	241	265	479	13	1032
Lying Down Front Seat	0	1	0	0	0	1
Lying Down Other Seat	2	2	2	1	0	7
Motorcycle Passenger	6	11	4	0	1	22
Other (explain in narrative)	3	10	24	9	0	46
Other Enclosed Area	1	0	0	2	0	3
Other Row (i.e. Bus, Van)	0	1	0	3	0	4
Passenger Front Row Left (Vehi	0	4	3	6	1	14
Riding on MV Exterior	0	1	1	0	0	2
Second Row Left	1	41	58	160	2	262
Second Row Middle	4	17	18	67	4	110
Second Row Right	9	44	72	208	1	334
Sleeper Section of Cab	5	13	11	13	0	42
Third Row Left	0	1	6	24	0	31
Third Row Middle	0	1	2	9	0	12
Third Row Right	0	2	7	25	0	34
Trailing Unit	0	1	0	2	0	3
Unknown (explain in narrative)	0	4	5	74	6	89
Total	327	1376	1523	2605	101	5932