## 2017 ALCOHOL INVOLVED PDO CRASHES WITH COLLISION TYPE

Collision Type	PDO Crashes	% PDO Crashes
Position de	2	0.5%
Barricade	2	0.5%
Bridge Overhead Structure	1 3	0.3%
Bridge Rail	-	0.8% 2.1%
Building or Other Structure Wall	8 1	2.1% 0.3%
Cable Barrier	1	
Cattle Guard	3	0.3%
Concrete Traffic Barrier/Jersey Barrier	ა 1	0.8%
Cut Slope	1	0.3%
Deer Parker Bast	9	0.3%
Delineator Post	-	2.3%
Ditch	11	2.8%
Earth Embankment/Berm	2	0.5%
Elk	1	0.3%
Fence (including Post)	29	7.5%
Guardrail End	5	1.3%
Guardrail Face	13	3.3%
Mail Box	6	1.5%
Motor Vehicle in Transport on Roadway	89	22.9%
Other Fixed Object	6	1.5%
Other NON-Fixed Object	12	3.1%
Other Non-Collision (MC Loss of Control)	1	0.3%
Other Traffic Barrier (includes temporary)	2	0.5%
Other Traffic Sign Support	2	0.5%
Overturn/Rollover	20	5.1%
Parked Motor Vehicle	99	25.4%
Raised Median or Curb	13	3.3%
Rock, Boulder, Rock Slide	5	1.3%
Sign Support Multiple Post	1	0.3%
Sign Support Single Post	7	1.8%
Snow Embankment	4	1.0%
Traffic Sign Support	5	1.3%
Traffic Signal Support	1	0.3%
Trees/Shrubbery	7	1.8%
Utility Pole/Light Support	16	4.1%
Work Zone Channeling Device	2	0.5%
Total	389	100%