

2017 TRUCK CRASHES

COLLISION TYPE / CRASH SEVERITY

| Collision Type | Fatal Crashes | Injury Crashes | PDO Crashes | Total Crashes |
|--|------------------|-------------------|----------------|------------------|
| Bridge Overhead Structure | 0 | 0 | 3 | 3 |
| Bridge Rail | 0 | 2 | 7 | 9 |
| Building or Other Structure Wall | 0 | 0 | 2 | 2 |
| Cable Barrier | 0 | 4 | 25 | 29 |
| Cargo/Equipment Loss of Shift | 1 | 1 | 22 | 24 |
| Cattle Guard | 0 | 0 | 1 | 1 |
| Concrete Traffic Barrier/Jersey Barrier | 0 | 0 | 6 | 6 |
| Deer | 0 | 0 | 1 | 1 |
| Delineator Post | 0 | 2 | 15 | 17 |
| Ditch | 0 | 2 | 5 | 7 |
| Earth Embankment/Berm | 0 | 1 | 8 | 9 |
| Elk | 0 | 0 | 3 | 3 |
| Equipment Failure | 1 | 3 | 27 | 31 |
| Fence (including Post) | 0 | 4 | 17 | 21 |
| Fire/Explosion | 0 | 1 | 32 | 33 |
| Guardrail End | 0 | 0 | 1 | 1 |
| Guardrail Face | 0 | 9 | 17 | 26 |
| Impact Attenuator/Crash Cushion | 0 | 0 | 1 | 1 |
| Jackknife | 0 | 17 | 240 | 257 |
| Mail Box | 0 | 0 | 1 | 1 |
| Motor Vehicle in Transport on OTHER Roadway | 0 | 0 | 2 | 2 |
| Motor Vehicle in Transport on Roadway | 11 | 119 | 462 | 592 |
| Object Set in Motion by Another Vehicle (Single Ve | 0 | 0 | 2 | 2 |
| Other Fixed Object | 0 | 0 | 3 | 3 |
| Other NON-Fixed Object | 0 | 0 | 9 | 9 |
| Other Non-Collision (MC Loss of Control) | 0 | 0 | 2 | 2 |
| Other Traffic Barrier (includes temporary) | 0 | 0 | 1 | 1 |
| Other Traffic Sign Support | 0 | 0 | 1 | 1 |
| Overturn/Rollover | 4 | 85 | 132 | 221 |
| Parked Motor Vehicle | 0 | 7 | 54 | 61 |
| Pedestrian | 1 | 1 | 0 | 2 |
| Road Approach | 0 | 1 | 1 | 2 |
| Sign Support Single Post | 0 | 1 | 3 | 4 |
| Snow Embankment | 0 | 0 | 3 | 3 |
| Traffic Sign Support | 0 | 0 | 2 | 2 |
| Traffic Signal Support | 0 | 0 | 4 | 4 |
| Utility Pole/Light Support | 0 | 1 | 7 | 8 |
| Work Zone Channeling Device | 0 | 0 | 7 | 7 |
| Work Zone/Maintenance Equipment | 0 | 0 | 1 | 1 |
| | 18 | 261 | 1130 | 1409 |