

**2018 NON-ALCOHOL INVOLVED PDO CRASHES
WITH COLLISION TYPE**

Collision Type	PDO Crashes	% PDO Crashes
Antelope	5	0%
Barricade	7	0%
Bridge Overhead Structure	20	0%
Bridge Pier or Support	4	0%
Bridge Rail	23	0%
Building or Other Structure Wall	26	0%
Cable Barrier	138	2%
Cargo/Equipment Loss of Shift	31	0%
Cattle Guard	7	0%
Concrete Traffic Barrier/Jersey Barrier	36	0%
Cow	5	0%
Cut Slope	6	0%
Deer	33	0%
Delineator Post	146	2%
Ditch	48	1%
Earth Embankment/Berm	50	1%
Elk	2	0%
End of Drainage Pipe/Structure/Culvert	15	0%
Equipment Failure	85	1%
Fell/Jumped from a MV	1	0%

Collision Type	PDO Crashes	% PDO Crashes
Fence (including Post)	328	4%
Fire/Explosion	66	1%
Guardrail End	21	0%
Guardrail Face	199	3%
Horse	1	0%
Immersion	2	0%
Impact Attenuator/Crash Cushion	1	0%
Jackknife	236	3%
Mail Box	25	0%
Moose	3	0%
Motor Vehicle in Transport on OTHER Roadway	1	0%
Motor Vehicle in Transport on Roadway	4072	52%
Object Set in Motion by Another Vehicle (Single Veh Crash)	21	0%
Other Domestic (Dog, Llama...)	3	0%
Other Fixed Object	69	1%
Other NON-Fixed Object	153	2%
Other Non-Collision (MC Loss of Control)	28	0%
Other Traffic Barrier (includes temporary)	5	0%
Other Traffic Sign Support	2	0%
Other Wild	1	0%
Overhead Traffic Sign	1	0%
Overturn/Rollover	527	7%

Collision Type	PDO Crashes	% PDO Crashes
Parked Motor Vehicle	1008	13%
Railway Vehicle	1	0%
Raised Median or Curb	48	1%
Road Approach	1	0%
Rock, Boulder, Rock Slide	15	0%
Sign Support Multiple Post	25	0%
Sign Support Single Post	56	1%
Snow Embankment	30	0%
Thrown or Falling Object	7	0%
Traffic Sign Support	38	0%
Traffic Signal Support	15	0%
Trees/Shrubbery	60	1%
Tunnel	1	0%
Unknown	4	0%
Utility Pole/Light Support	104	1%
Work Zone Channeling Device	33	0%
Work Zone/Maintenance Equipment	4	0%
Total	7903	100%