

**2018 ALCOHOL INVOLVED PDO CRASHES
WITH COLLISION TYPE**

Collision Type	PDO Crashes	% PDO Crashes
Bridge Pier or Support	1	0%
Bridge Rail	6	2%
Building or Other Structure Wall	5	1%
Cable Barrier	5	1%
Cattle Guard	1	0%
Concrete Traffic Barrier/Jersey Barrier	6	2%
Cut Slope	2	1%
Deer	1	0%
Delineator Post	15	4%
Ditch	4	1%
Earth Embankment/Berm	6	2%
Elk	1	0%
End of Drainage Pipe/Structure/Culvert	1	0%
Equipment Failure	1	0%
Fence (including Post)	37	9%
Guardrail End	3	1%
Guardrail Face	5	1%
Mail Box	1	0%
Motor Vehicle in Transport on Roadway	105	27%
Other Fixed Object	10	3%
Other NON-Fixed Object	4	1%
Overturn/Rollover	27	7%
Parked Motor Vehicle	79	20%
Raised Median or Curb	5	1%
Rock, Boulder, Rock Slide	4	1%
Sign Support Multiple Post	1	0%
Sign Support Single Post	7	2%
Snow Embankment	3	1%
Traffic Sign Support	11	3%
Traffic Signal Support	2	1%
Trees/Shrubbery	16	4%
Unknown	3	1%
Utility Pole/Light Support	15	4%
Work Zone Channeling Device	2	1%
Work Zone/Maintenance Equipment	1	0%
Total	396	100%