

**2018 OCCUPANTS IN INJURY CRASHES
WITH SEAT POSITION / INJURY STATUS**

	Suspected Serious	Suspected Minor	Possible	No Injury	Unknown	Total
Bus Passenger	0	1	2	20	0	23
Driver	200	1008	1063	1472	51	3794
Fourth Row Left	2	0	0	3	0	5
Fourth Row Middle	0	3	0	2	0	5
Fourth Row Right	0	1	0	0	0	1
Front Row Middle	2	3	4	4	0	13
Front Row Right	34	208	232	418	8	900
Lying Down Other Seat	2	3	1	3	0	9
Motorcycle Passenger	4	6	7	0	0	17
Other (explain in narrative)	2	1	1	14	0	18
Other Enclosed Area	1	2	1	0	0	4
Other Row (i.e. Bus, Van)	1	0	1	0	0	2
Passenger Front Row Left (Vehi	1	2	4	3	0	10
Second Row Left	4	39	40	150	4	237
Second Row Middle	6	12	15	72	1	106
Second Row Right	5	35	47	181	5	273
Sleeper Section of Cab	3	15	16	16	0	50
Third Row Left	1	3	4	19	1	28
Third Row Middle	0	2	6	4	0	12
Third Row Right	1	5	5	19	1	31
Trailing Unit	0	0	0	1	0	1
Unknown (explain in narrative)	1	8	6	124	5	144
Total	270	1357	1455	2525	76	5683