

2018 CRASHES
ROAD CIRCUMSTANCES

Road Circumstances	Fatal Crashes			Injury Crashes			PDO Crashes			Total Crashes		
	Road Circumstances Choice									1st	2nd	3rd
	1st	2nd	3rd	1st	2nd	3rd	1st	2nd	3rd			
Debris, loose material on the surface	1	0	0	29	4	0	59	8	0	89	12	0
Lane Markings Missing or Faded	0	0	0	1	0	0	9	3	0	10	3	0
Non-Highway Work	0	0	0	0	0	0	1	0	0	1	0	0
None	83	0	0	1993	0	0	6293	0	0	8369	0	0
Obstructed by a Previous Crash	0	0	0	2	2	1	10	9	1	12	11	2
Obstruction in Roadway	0	0	0	2	0	0	25	5	1	27	5	1
Other	0	0	0	4	0	0	27	8	1	31	8	1
Reduced Road Width	0	0	0	0	3	0	6	4	0	6	7	0
Road Surface Condition	13	1	0	331	0	2	1547	5	1	1891	6	3
Ruts, Holes, Bumps	1	0	0	14	5	2	28	7	0	43	12	2
Shoulders (None, Low, Soft, High)	0	0	0	9	3	0	13	1	1	22	4	1
Traffic Control Device Inoperative	0	0	0	1	0	0	1	1	0	2	1	0
Traffic Control Device Missing	0	0	0	1	2	0	3	0	0	4	2	0
Traffic Control Device Obscured	0	0	0	1	1	0	3	2	0	4	3	0
Unknown	1	0	0	16	0	0	153	0	0	170	0	0
Work Zone/Construction Zone	1	0	0	26	2	0	110	5	0	137	7	0
Worn or Polished Surface	0	0	0	2	2	0	11	2	0	13	4	0
Total	100	1	0	2432	24	5	8299	60	5	10831	85	10

NOTE: Every crash can have three road circumstance choices.

NOTE: Road Circumstances not collected on PDO Animal crash form or Owner/Operator crash form.